

Oil Field Environmental Incident Summary

Incident: 20160307140702 **Date/Time of Notice:** 03/07/2016 14:07

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: LONG 1-01H

Field Name: PARSHALL

Well File #: 16637

Date Incident: 3/6/2016 **Time Incident:** 16:51

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 1

Qtr:

Location Description: A treater caught fire on-site and resulted in an offsite grass fire as well. Grass area burned was approximately 305 sq. ft.

Submitted By: Brenda Vaness

Received By:

Contact Person: Brenda Vaness
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/16/2016

Clean Up Concluded: 3/11/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Emergency services were contacted and the fire department extinguished the fire with water and foam. There is some residual oil, production water (non-reportable amounts) and fire dispersant that were contained in the treater berm. The treater and any contaminated material will be removed and disposed of.

Wastes Disposal Location: TBD

Agencies Involved: Local Fire Department

Updates

Date: 3/7/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the type of incident was a fire that remained on the facility site. NDIC retains oversight.